



BRUHAT BENGALURU MAHANAGARA PALIKE

No.AEE/HBR/PR/ 98 /2023-24

Office of the Asst Executive Engineer,
HBR Layout Sub-division
5th Main 3rd Block, HBR Layout
BBMP, Bangalore-560043
Date: 02-08-2023

BUILDING SAFETY CERTIFICATE

Sub: Building Certificate


Ref:-1. HMR International School Letter Dated: 06.07.2023

2. Structural Soundness Certificate (Building Certificate)

Issued by Right Angle Architects and Interior Designers.

Dated: 28.07.2023.

With Reference to the above Subject, regarding Building Certificate of the existing School building of HMR INTERNATIONAL SCHOOL, No.41/1, 9th Main, 11th Cross, HBR 4th Block, Hennur Maruthi Layout, Bengaluru-560043. This is certified that as per reference (2) Structural Soundness Certificate (Building Certificate) Issued by Right Angle Architects and Interior Designers. Dated: 28.07.2023. We have Inspected the School on 29.07.2023 along with the School Staff. Based on the Certificate issued under reference (2) Building is Structurally Sound and fit for Running School.


Assistant Executive Engineer,
HBR Layout Sub-Division
Bruhat Bengaluru Mahanagara Palike

To,

Head of the Institution,
HMR International School
No.41/1, 9th Main, 11th Cross,
Hennur Maruthi Layout
HBR 4th Block, (Hennur Cross)
Kalyan Nagar Post Bangalore-560043